



2008 Hawker 900XP N1776C S/N HA0002

Hawker 900XP S/N HA0002

HIGHLIGHTS

- Collins Pro Line 21 Avionics Suite
- Gogo AVANCE L3 Internet Wi-Fi
- Engines Enrolled on Honeywell MSP Gold
- APU Enrolled on Honeywell MSP Gold
- Collins Avionics Enrolled on CASP
- Eight Passenger Executive Seating
- 9th Passenger Belted Lavatory Seat
- Dual Collins IFIS 5010 File Servers
- Galley WaveJet SL Microwave
- TCAS II with Change 7.1
- ADS-B Out
- WAAS/LPV

AIRFRAME

TOTAL TIME 4,558.2 Hours
LANDINGS 2,828

ENGINES

Honeywell TFE 731-50R-1H

	Engine #1	Engine #2
Serial Number	P122109	P122108
Total Time Since New	4,490.2 Hours	4,490.2 Hours
Cycles Since New	2,799	2,799

Engines Enrolled on Honeywell MSP Gold

AUXILIARY POWER UNIT

Honeywell GRT GTCP36-150 (W)

Serial Number	P-970
Total Time Since New	3,203 Hours
Cycles Since New	1,085

APU Enrolled on Honeywell MSP Gold



Hawker 900XP S/N HA0002

AVIONICS

Collins Pro Line 21 Avionics Suite

Dual Collins FMC-6000 FMS Control Modules

Dual Collins GPS-4000S GPS Sensors

Dual Collins ADC-3000 Air Data Computers

Collins NAV-4000 Navigation Receiver

Dual Collins ADC-3000 Air Data Computers

Dual Collins TDR-94D Mode S Transponders

Collins FGP-3000 Flight Guidance Panel

Dual Collins DCP-3040 Flight Guidance Control Panels

Dual Collins DCU-3001 Data Concentrator Units

Dual Collins DME-4000 Distance Measuring Units

Collins DBU-5010 Data Base Unit

Collins TCAS 94 TTR-4000 TCAS II w/7.1

Collins MDC-3110 Maintenance Diagnostic Computer

Honeywell Mark V Enhanced Ground Proximity System

Collins RTA-858 Weather Radar

Four Collins AFD-3010 Adaptive Flight Displays

Dual Collins CDU-6200 Control Display Units

Collins IFIS FSU-5010 File Server

Second Collins IFIS FSU-5010 File Server Option

Collins NAV-4500 Navigation Receiver

Dual Collins AHC-3000 ARHS Units

Dual Collins VHF-4000 Comm. Transceivers

Dual Collins FGC-3000 Flight Guidance Control Modules

Collins ALT-4000 Radio Altimeter

Dual Collins CCP-3000 Cursor Control Panels

Collins HF-9031A HF Communication System w/SELCAL

AvTech SCD-714 SELCAL Decoder

Collins AFIS

Universal CVR-120 Cockpit Voice Recorder

Electronic Secondary Flight Display

Artex C406-N Emergency Locator Transmitter



Hawker 900XP S/N HA0002

AVIONICS UPGRADES / CERTIFICATIONS / CAPABILITIES

RVSM

TCAS II w/Change 7.1

ADS-B Out

WAAS/LPV

Data Link Comm. w/ACARS

Class A TAWS

Mode S Enhanced Surveillance

VHF Comm. 8.33 MHz Spacing

NAV FM Immunity

ADDITIONAL EQUIPMENT / UPGRADES

Winglets

Boom Beam Taxi/Landing Lights

Precise Flight Pulselite System

Concorde Main Batteries

Fight Deck 115 Volt AC Outlet

Therapeutic Oxygen Port & Mask

Dual 750 Liter Oxygen Bottles

Galley Lighted Crystal Storage Rack Area

WaveJet SL Microwave Oven

Fabric Engine Covers

Windshield Sunshield Set

Goodrich Wheels & Brakes

Tail Logo Lights

Airstair LED Courtesy Lights

Yoke Mounted Chart Holders

Cockpit Speaker Inhibit Switch

Passenger Address/Combined Chimes

Flight Deck Rosen Sun Visors

Galley Cold Storage

Dual Coffee Canister Rack

Forward Baggage Umbrella Storage Rack



Hawker 900XP S/N HA0002

ENTERTAINMENT / CONNECTIVITY

Gogo AVANCE L3 Internet Wi-Fi System
Aircell ST-3100 Iridium Phone System
Rockwell Collins Dual Disc DVD Player
Forward & Aft Bulkhead Monitors

Airshow 4000
Flight Deck & Cabin Aircell Phone Handsets
Cabin 115 Volt AC Power Outlets
Cabin Management Switching System

INTERIOR CONFIGURATION

Eight Passenger Executive Interior
Forward Cabin Four Place Executive Club Seats
Left Forward Well-Equipped Galley
Two Executive Pull-Out Tables
Aft Lavatory & Privacy Door
Forward Left-Hand Crew Storage Cabinet

Nineth Passenger Belted Lavatory Seat
Left Aft Three-Place Divan Across from Single Executive Seat
Right Forward Large Baggage Area
Right Aft Cabin Closet w/Pass-Through to Lavatory Baggage
Lavatory Vanity & Sink
Lavatory Lighted Mirror

CUSTOM PAINT

Matterhorn White Base
Tan Stripes Accent Stripes



Hawker 900XP S/N HA0002

MAINTENANCE STATUS

	Complied With	Next Due
B Inspection – 800 Hour	9/2022 @ 4,002 Hours	4,802 Hours
C Inspection – 1600 Hour	3/2019 @ 3,190 Hours	4,773 Hours
D Inspection – 3200 Hour	3/2019 @ 3,190 Hours	6,390 Hours
E Inspection – 12 Month	12/2024 @ 4,533 Hours	12/2025
F Inspection – 24 Month	12/2023 @ 4,348 Hours	12/2025
G Inspection – 48 Month	12/2023 @ 4,348 Hours	12/2027
400 Hour Walk Around	12/2023 @ 4,348 Hours	4,748 Hours
Landing Gear Overhaul	12/2019 @ 2,131 Landings	12/2031 or 7,131 Landings



Hawker 900XP S/N HA0002



Axiom Aviation, Inc. | (216) 261-8934 | Cuyahoga County Airport | Cleveland, Ohio | www.AxiomAv.com

Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Hawker 900XP S/N HA0002



Axiom Aviation, Inc. | (216) 261-8934 | Cuyahoga County Airport | Cleveland, Ohio | www.AxiomAv.com



ANDY TOY | ANDY@AXIOMAV.COM

Mobile (440) 227-1466 (Direct) | Axiom Office (216) 261-8934

Axiom Aviation, Inc. | Cuyahoga County Airport | Cleveland, Ohio | www.AxiomAv.com

These specifications are presented as introductory information only. They do not constitute representations or warranties of any kind. Accordingly, purchaser should rely on their own inspection of this aircraft. This aircraft availability is subject to prior sale, and/or removal from the market.

